## P.I.C. WELDING ADHESIVE

COLORS: WHITE

**CLEAR** 

DESCRIPTION: P.I.C. adhesive is used as a component for bonding P.I.C.

sheeting, jackets, and fitting covers.

WEIGHT: 8 LBS per gallon

2.5 LBS per quart

SPECIFICATION COMPLIANCE: USDA accepted.

APPLICATION: Use in P.I.C. applicator dispenser or approved hand pump

oiler. Thin only as necessary with P.I.C.'s welding thinner.

(Refer to application instructions in brochure.)

LIMITATIONS: To avoid excessive evaporation of adhesive, do not apply

with brush. Do not use as a filler in gaps or joints as

adhesive will soften PVC. Apply between 40° F and 100° F.

Below 40° F allows longer set-up time.

COVERAGE: One gallon per 500 lineal feet of jacketing.

CAUTION: Extremely flammable. Keep away from heat, sparks, and

open flame. Avoid prolonged contact with skin and breathing of vapor and spray mist. Do not take internally. Close container after each use. Keep out of reach of

children. For industrial use only.

CLEAN UP: P.I.C. thinner can be used for clean up and for removal of

adhesive from applicator guns.

For additional information, refer to labels on P.I.C.'s welding adhesive and welding adhesive thinner containers. Also, refer to material safety data sheet.